

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



**Location Overview: Location is approximately 86 yards from
Pete & Bill creek. Location is within High Priority/Black
Bear/NSO Habitat areas.**

Section/Township/Range: 8 8S95W

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



Photo # 6621 Erosion & transport of sediment (N/NE area of location on slope near wellheads)



Photo # 6622 Erosion & transport of sediment (N/NE area of location on slope near wellheads)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



Photo # 6623 Erosion & transport of sediment (N/NE area of location on slope near wellheads)



Photo # 6624 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



Photo # 6631 Lack of stabilization/compaction



Photo # 6636 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



Photo # 6642 Lack of stabilization/compaction



Photo # 6644 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



Aug 21, 2023 at 8:54:59 AM
CO

Photo # 6637 Lack of stabilization on cut slope (S/SE area of location)



Aug 21, 2023 at 8:55:09 AM
CO

Photo # 6638 Lack of stabilization on cut slope (S/SE area of location)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



Photo # 6647 Lack of stabilization on cut slope (S/SE area of location)



Photo # 6652 Lack of stabilization on cut slope (S/SE area of location)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



Aug 21, 2023 at 8:58:52 AM
CO

Photo # 6654 Lack of stabilization on cut slope (S/SE area of location)



Aug 21, 2023 at 8:59:01 AM
CO

Photo # 6656 Lack of stabilization on cut slope (S/SE area of location)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



Photo # 6690 Tunnel erosion/sink hole (near entrance to location)



Photo # 6660

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SGV FEDERAL 8D Pad
Location ID: 415673



Photo # 6664



Photo # 6665