

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/21/2023

Submitted Date:

08/30/2023

Document Number:

708901444

FIELD INSPECTION FORM
 Loc ID 335243 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

24 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211125	WELL	PR	12/22/1995	GW	045-06884	COOK RW 5-29	PR
256342	WELL	PR	10/27/1999	GW	045-07441	SAVAGE RWV 129-29	PR
295182	WELL	PR	02/20/2009	GW	045-15693	SAVAGE RWF 443-29	PR
295183	WELL	PR	10/19/2008	GW	045-15694	Savage RWF 334-29R	PR
295184	WELL	PR	01/31/2009	GW	045-15695	SAVAGE RWF 434-29	PR
295185	WELL	PR	05/01/2014	GW	045-15696	SAVAGE RWF 34-29	PR
295186	WELL	PR	01/31/2009	GW	045-15697	SAVAGE RWF 533-29	PR
416355	WELL	PR	05/01/2014	GW	045-19254	SAVAGE RWF 433-29	PR
416356	WELL	PR	05/01/2022	GW	045-19255	SAVAGE RWF 33-29	PR
416360	WELL	PR	10/01/2011	GW	045-19256	SAVAGE RWF 444-29	PR
416361	WELL	PR	12/01/2022	GW	045-19257	SAVAGE RWF 543-29	PR
416363	WELL	PR	10/01/2011	GW	045-19258	SAVAGE RWF 344-29	PR

General Comment:

CECMC Inspection Report Summary

On 08/21/2023 at approximately 14:50 hours, I, Compliance Specialist, Wayne Smelser
Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC SAVAGE RMV 129-29 Pad.

Location # 335243 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas & Bald Eagle Nest/Roost Site & in close proximity to NSO habitat area.

Location is approximately 244 yards from the Colorado River.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Housekeeping - Stained soils & gravel on location with a CA date of 09/09/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Split pad/remote location - Wellheads only, separator units & production tanks are located on the SAVAGE RU 28 Pad, location # 335291

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:	No tank battery on location			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/970-285-9377			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Stained soils & gravel near wellheads			
Corrective Action:	Remove and properly dispose of all stained soils and gravel.			Date: 09/09/2023
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Hog panels			
Corrective Action:				Date:
Equipment:				
				corrective date
Type: Bradenhead	# 12			
Comment:	RWF 34-29 & RWF 344-29 wells have Taylor plugs located on bradenheads, bradenhead valves are accessible.			
Remaining 10 wells have no form of pressure monitoring equipment located on bradenheads. All bradenhead valves are accessible.				
Corrective Action:				Date:
Type: Plunger Lift	# 12			
Comment:	All wells on plunger lift			
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

--	--	--	--

Inspected Facilities									
Facility ID:	211125	Type:	WELL	API Number:	045-06884	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	256342	Type:	WELL	API Number:	045-07441	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	295182	Type:	WELL	API Number:	045-15693	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	295183	Type:	WELL	API Number:	045-15694	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	295184	Type:	WELL	API Number:	045-15695	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	295185	Type:	WELL	API Number:	045-15696	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	295186	Type:	WELL	API Number:	045-15697	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	416355	Type:	WELL	API Number:	045-19254	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Facility ID:	416356	Type:	WELL	API Number:	045-19255	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	416360	Type:	WELL	API Number:	045-19256	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	416361	Type:	WELL	API Number:	045-19257	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	416363	Type:	WELL	API Number:	045-19258	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Light compaction
Gravel						Sparse
		Culverts				
		Ditches				
		Compaction				
		Gravel				Sparse

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Housekeeping for observed compliance issue.	smelserw	08/24/2023
Split pad/remote location - Wellheads only, separator units & production tanks are located on the SAVAGE RU 28 Pad, location # 335291		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901445	Inspection 708901444 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6237846
708901446	Inspection 708901444 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6237847