

Inspection Photos

Location Name: CAERUS PICEANCE LLC SGV 7K Pad

Location ID: 334366



Photo # 6855 From entrance to location



Photo # 6856 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC SGV 7K Pad
Location ID: 334366



Photo # 6863 Location



Photo # 6864 Location



Inspection Photos
Location Name: CAERUS PICEANCE LLC SGV 7K Pad
Location ID: 334366



Photo # 6865 Location



Photo # 6866 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC SGV 7K Pad
Location ID: 334366



Photo # 6854 Location



Photo # 6871 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC SGV 7K Pad
Location ID: 334366



Inspection Photos
Location Name: CAERUS PICEANCE LLC SGV 7K Pad
Location ID: 334366



Photo # 6870 Open ended load line



Photo # 6872 Open ended load line

Inspection Photos

Location Name: CAERUS PICEANCE LLC SGV 7K Pad

Location ID: 334366



Photo # 6869 Debris



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources