

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-07 Pad

Location ID: 334388



**Photo # 7088 From entrance to location**



**Photo # 7089 Location**





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-07 Pad

Location ID: 334388



Photo # 7090 Location



Photo # 7091 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-07 Pad

Location ID: 334388



**Photo # 7094 Location**



**Photo # 7095 Location**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-07 Pad

Location ID: 334388



**Photo # 7096 Improperly marked deadman**



**Photo # 7107 Unmarked deadman**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-07 Pad

Location ID: 334388



**Photo # 7111 Methanol tank lacks required information**



**Photo # 7112 Methanol tank lacks required information**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-07 Pad

Location ID: 334388



**Photo # 7115 Hole in liner/liner needs maintenance**



**Photo # 7116 Hole in liner/liner needs maintenance**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-07 Pad

Location ID: 334388



**Photo # 7118 Hole in liner/liner needs maintenance**




**Photo # 7119 Hole in liner/liner needs maintenance**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-07 Pad

Location ID: 334388



**Photo # 7121 Hole in liner/liner needs maintenance**



**Photo # 7122 Hole in liner/liner needs maintenance**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-07 Pad

Location ID: 334388



**Photo # 7124 Hole in liner/liner needs maintenance**



**Photo # 7125 Hole in liner/liner needs maintenance**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-07 Pad

Location ID: 334388



**Photo # 7126 Hole in liner/liner needs maintenance**



**Photo # 7127 Hole in liner/liner needs maintenance**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-07 Pad

Location ID: 334388



Photo # 7128 Debris



Photo # 7131 Debris



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Johnson 5-07 Pad

Location ID: 334388



Photo # 7098 Debris



Photo # 7136 PRV vent lacks cap