

Inspection Photos
Location Name: CAERUS PICEANCE LLC I18 Pad
Location #: 334866



Photo # 7435 From entrance to location



Photo # 7436 Location



Inspection Photos
Location Name: CAERUS PICEANCE LLC I18 Pad
Location #: 334866



Photo # 7439 Location



Photo # 7440 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC I18 Pad
Location #: 334866



Photo # 5161 From inspection 708901316 conducted on 08/08/2023 Open ended load line



Photo # 7445 Open ended load line

Inspection Photos
Location Name: CAERUS PICEANCE LLC I18 Pad
Location #: 334866



Photo # 7444 Debris