

Final Reclamation and Stormwater Inspection

Date: 08/23/2023

Operator: SCHNEIDER ENERGY SERVICES INC - 76840

Location ID: 313914

Inspection Document #: 708200515

Morgan County, CO

SWSW Section 21 T6N R59W

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Muir 13A
Location ID: 313914



Photo 1. Taken near the former well location. Debris (fence posts) remain on location and there is evidence of non-uniform vegetation cover resulting in bare/exposed soils. Additional reclamation activities are required in order to comply with Rule 1004.

Inspection Photos
Location Name: Muir 13A
Location ID: 313914



Photo 2. Taken from the western portion of the well location; see comments in Photo 1.

Inspection Photos
Location Name: Muir 13A
Location ID: 313914



Photo 3. Taken from the eastern portion of the location; see comments in Photo 1.

Inspection Photos
Location Name: Muir 13A
Location ID: 313914



Photo 4. Taken on the east-west lease road. Heavy rutting on the former access road (obscured by vegetation) will require additional reclamation activities in order to comply with Rule 1004.

Inspection Photos
Location Name: Muir 13A
Location ID: 313914



Photo 5. Taken near the former separator location. Gravel and road base material remain on the location and requires removal to comply with Rule 1004.

Inspection Photos
Location Name: Muir 13A
Location ID: 313914



Photo 6. Taken near the former tank battery location; Gravel and road base material remain on the location and requires removal to comply with Rule 1004.

Inspection Photos
Location Name: Muir 13A
Location ID: 313914



Photo 7. Taken from the north-south access road. Heavy rutting on the former access road (obscured by vegetation) will require additional reclamation activities in order to comply with Rule 1004.

Inspection Photos
Location Name: Muir 13A
Location ID: 313914



Photo 8. Google Earth aerial imagery taken circa 12/2019. Photo illustrates the access roads that require additional reclamation activities to comply with Rule 1004. During this inspection, Staff walked both access roads and observed that re-grading and contouring is required as heavy rutting (as deep as 1') was evident.