


**APEX Oil Ventures Inc
Gillam-Trigood-Gov't 14
Loc ID: 314769**



No gas sales. All gas being flared.



Weeds

**APEX Oil Ventures Inc
Gillam-Trigood-Gov't 14
Loc ID: 314769**



Random debris



Weeds

**APEX Oil Ventures Inc
Gillam-Trigood-Gov't 14
Loc ID: 314769**



Stormwater BMPs need implementation and maintenance.



Weeds. Sediment migration. Stormwater BMP not maintained.

**APEX Oil Ventures Inc
Gillam-Trigood-Gov't 14
Loc ID: 314769**



Location view from Southwest corner



Location view from Northwest corner

**APEX Oil Ventures Inc
Gillam-Trigood-Gov't 14
Loc ID: 314769**



Location view from Southeast corner



Location view from Northeast corner

**APEX Oil Ventures Inc
Gillam-Trigood-Gov't 14
Loc ID: 314769**



Debris. Lack of Stormwater BMPs



Debris

**APEX Oil Ventures Inc
Gillam-Trigood-Gov't 14
Loc ID: 314769**



Debris




Debris

**APEX Oil Ventures Inc
Gillam-Trigood-Gov't 14
Loc ID: 314769**



Tank battery. Stormwater BMPs not in place.



Debris

**APEX Oil Ventures Inc
Gillam-Trigood-Gov't 14
Loc ID: 314769**



Stained soil at loadout.



Debris

**APEX Oil Ventures Inc
Gillam-Trigood-Gov't 14
Loc ID: 314769**



Southeast corner view of tank battery



Southwest corner view of tank battery

**APEX Oil Ventures Inc
Gillam-Trigood-Gov't 14
Loc ID: 314769**



Northeast corner view of tank battery



Northwest of tank battery. Looking up from loadout.