

Inspection Photos

API: 041-06051

Operator: ETOCO LP

Inspection Date: 8/23/2023



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 041-06051 | Date: 8/23/2023

Inspection Photos



Photo 1. Facing south along the former access road which has not established vegetation. There are some signs of erosion along the road.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 041-06051 | Date: 8/23/2023

Inspection Photos



Photo 2. Facing south along the former access road which has not established vegetation. There are some signs of erosion along the road.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 041-06051 | Date: 8/23/2023

Inspection Photos



Photo 3. Center of the location facing south.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 041-06051 | Date: 8/23/2023

Inspection Photos



Photo 4. Center of the location facing north.



Inspection Photos



Photo 5. Center of the location facing east.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 041-06051 | Date: 8/23/2023

Inspection Photos



Photo 6. Center of the location facing west.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 041-06051 | Date: 8/23/2023