

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/17/2023

Submitted Date:

08/29/2023

Document Number:

701103805

FIELD INSPECTION FORM
 Loc ID 335643 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284599	WELL	PR	01/01/2019	GW	045-12225	CASCADE CREEK 697-16-37D	EG

General Comment:
 Flowline integrity inspection:
 Unused equipment (flowlines)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	2 – 4" unused flowlines at north west edge of location that run to south edge of Pond G.		
Corrective Action:	<p>Comply with Rule 606</p> <p>Ensure flowline(s) are isolated and depressurized; associated wells and isolation valves are SI/ OOSLAT to prevent unintentional release per 1102.j.7</p> <p>Identify and report flowlines status, purpose and where the lines end at.</p> <p>Work with CECMC Flowline Integrity group to Abandon flowlines in accordance of Rule 1105</p>		Date: <u>09/30/2023</u>

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 284599 Type: WELL API Number: 045-12225 Status: PR Insp. Status: EG**Flowline**

#1	Type:	2 of Lines
----	-------	------------

Flowline Description

Flowline Type: Size: 4" Material: Carbon Steel
Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: 2 – 4" unused flowlines at north west edge of location running to Pond G location.

Corrective Action: Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103806	Map of unused flowlines	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6239812
701103807	Flowline integrity inspection 701103805 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6239813