



Inspection Photos
well 057-06139
Inspection
Date:8/18/2023

All Photos taken
by Kris Neidel

Photo #1 wellhead was fenced with pump rods.



Inspection Photos
well 057-06139
Inspection
Date:8/18/2023

All Photos taken
by Kris Neidel

Photo #2 flowline on ground. Soil built up at wellhead had oil staining.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
well 057-06139
Inspection
Date:8/18/2023

All Photos taken
by Kris Neidel

Photo #3 Tank near well. Tank was fenced.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
well 057-06139
Inspection
Date:8/18/2023

All Photos taken
by Kris Neidel

Photo #4 overview of Tank. Tank did not have adequate secondary containment. Soil type at tank is Sand.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
well 057-06139
Inspection
Date:8/18/2023

All Photos taken
by Kris Neidel

Photo #5 overview of Tank. Tank did not have adequate secondary containment. Soil type at tank is Sand.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
well 057-06139
Inspection
Date:8/18/2023

All Photos taken
by Kris Neidel

Photo #6 photo showing proximity of tank to well. .