



Inspection Photos
well 057-06376

Inspection
Date:8/18/2023

All Photos taken
by Kris Neidel

Photo #1 Sign at wellhead.





Photo #2 Well fenced.

Inspection Photos
well 057-06376

Inspection
Date:8/18/2023

All Photos taken
by Kris Neidel





Inspection Photos
well 057-06376

Inspection
Date:8/18/2023

All Photos taken
by Kris Neidel

Photo #3 condition of wellhead.





Inspection Photos
well 057-06376

Inspection
Date:8/18/2023

All Photos taken
by Kris Neidel

08.18.2023 10:33

Photo #4 Another view of well.





08.18.2023 10:34

Inspection Photos
well 057-06376

Inspection
Date:8/18/2023

All Photos taken
by Kris Neidel

Photo #5 Tank Battery near well. Tank is fenced. It was not obvious that this tank has adequate secondary containment.





Photo #6 erosion under tank.

**Inspection Photos
well 057-06376**

**Inspection
Date:8/18/2023**

**All Photos taken
by Kris Neidel**





Inspection Photos
well 057-06376

Inspection
Date:8/18/2023

All Photos taken
by Kris Neidel

Photo #7 Tank.





Inspection Photos
well 057-06376

Inspection
Date:8/18/2023

All Photos taken
by Kris Neidel

Photo #8 Plaquire on Tank.

