

# Inspection Photos

8/28/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 334745

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 334745



**Photo 1:** Photos 1-2 provide an overview of the working pad surface, from east, southeast, southwest to west.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 334745



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 334745



**Photo 3:** Photo taken from the northeast corner of the working pad surface. Photo shows control measures to allow for proper stormwater discharge remain missing or insufficient; erosion degradation has persisted.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 334745



August 28, 2023



August 28, 2023

**Photo 4:** Photo shows erosion degradation due to stormwater runoff from the northeast corner of the working pad surface, behind the tank battery. BMPs to properly manage runoff remain inadequate.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 334745



**Photo 5:** Photo taken from the sediment trap on the north east end of the Location. Photo shows outlet has not been installed per good engineering practices; rock armoring has not been installed in conjunction with geotextile lining, resulting in degradation to the control.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 334745



**Photo 6:** Photos shows sediment trap on the north east end of the Location has not been installed with a properly engineered inlet. Stormwater runoff from the pad is resulting in degradation to the control.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 334745



**Photo 7:** Photo shows contoured areas, on the north end of the working pad surface, that discharges stormwater into the interim areas to the north, and into the sediment trap observed within photos 5-6.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 334745



**Photo 8:** Photo taken from the northern interim areas. Vegetation within these areas are predominantly undesirable plant species.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 334745



**Photo 9:** Photo taken from the southern/western interim areas. Desirable vegetative establishment is more evident within these areas, though Undesirable Plant Species remain dominant.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources