

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NWSE

Location ID: 324063

Date: 8/22/2023



SE Corner of Location – Photo #06016



West Entrance to Location – Photo #06017

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NWSE

Location ID: 324063

Date: 8/22/2023



Wellhead – Photo #06018



Separator – Photo #06019

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NWSE

Location ID: 324063

Date: 8/22/2023



Tank Battery – Photo #06020



**Insufficient Erosion Control/Rill Erosion Running Onto
Location – Photo #06022**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NWSE

Location ID: 324063

Date: 8/22/2023



**Insufficient Erosion Control/Rill Erosion Running Onto
Location – Photo #06023**



Rill Erosion Cutting Through Access Road – Photo #06025

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/1NWSE

Location ID: 324063

Date: 8/22/2023



Rill Erosion Cutting Through Access Road – Photo #06026



Rill Erosion Cutting Through Access Road – Photo #06027