

Inspection Photos
Location Name: CAERUS PICEANCE LLC D32NEB Pad
Location #: 335301



Photo # 7662 From entrance to location



Photo # 7664 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC D32NEB Pad
Location #: 335301



Photo # 7665 Location



Photo # 7666 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC D32NEB Pad
Location #: 335301



Photo # 7669 Location




Photo # 7673 Stained gravel in secondary containment

Inspection Photos
Location Name: CAERUS PICEANCE LLC D32NEB Pad
Location #: 335301



Photo # 7674 Stained gravel in secondary containment



Photo # 7675 Stained gravel in secondary containment

Inspection Photos
Location Name: CAERUS PICEANCE LLC D32NEB Pad
Location #: 335301



Photo # 7680 Debris