

Inspection Photos

Location Name: CAERUS PICEANCE LLC I27W Pad

Location # 324383



Photo # 8043 From entrance to location



Photo # 8044 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC I27W Pad
Location # 324383



Photo # 8045 Location



Photo # 8049 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC I27W Pad
Location # 324383



Photo # 8046 Location



Photo # 8047 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC I27W Pad

Location # 324383



Photo # 8048 Location

Photo # 8058 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC I27W Pad
Location # 324383



Photo # 8069 MCU 26-4A well, gas is bubbling up from conductor

Photo # 8050 MCU 26-4A well, gas is bubbling up from conductor

Inspection Photos

Location Name: CAERUS PICEANCE LLC I27W Pad

Location # 324383



Photo # 8055 MCU 26-4A well, gas is bubbling up from conductor



Photo # 8078 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC I27W Pad
Location # 324383



Photo # 8087 Hole in secondary containment liner/liner needs maintenance



Photo # 8088 Liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC I27W Pad
Location # 324383



Photo # 8089 Liner needs maintenance



Photo # 8097 Bird protection on 500 bbl heated condensate tank needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC I27W Pad

Location # 324383



Photo # 8100 Bird protection on 500 bbl heated condensate tank needs maintenance



Photo # 8101 Bird protection on 500 bbl heated condensate tank needs maintenance