

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N22W Pad**  
**Location # 324286**



**Photo # 7976 From entrance to location**



**Photo # 7977 From entrance to location**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N22W Pad**  
**Location # 324286**



**Photo # 7978 Location**



**Photo # 7979 Location**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N22W Pad**  
**Location # 324286**



**Photo # 7980 Location**



**Photo # 7981 Location**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC N22W Pad**  
**Location # 324286**



**Photo # 7982 Debris**



**Photo # 8004 Debris**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC N22W Pad

Location # 324286



Photo # 8005 Debris & open ended load line



Photo # 8022 Debris



## Inspection Photos

Location Name: CAERUS PICEANCE LLC N22W Pad

Location # 324286



**Photo # 8007 Hole in liner/liner needs maintenance**



**Photo # 8008 Hole in liner/liner needs maintenance**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC N22W Pad

Location # 324286



**Photo # 8009 Liner needs maintenance**



**Photo # 8010 Liner needs maintenance**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC N22W Pad

Location # 324286



**Photo # 8011 Liner needs maintenance**



**Photo # 8012 Liner needs maintenance**





## Inspection Photos

Location Name: CAERUS PICEANCE LLC N22W Pad

Location # 324286



Photo # 8013 Flowline heating insulation open ended



Photo # 8014 Flowline heating insulation open ended



## Inspection Photos

Location Name: CAERUS PICEANCE LLC N22W Pad

Location # 324286



**Photo # 8015 Flowline heating insulation open ended**