


**Storm Water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N22W Pad**  
**Location # 324286**



**Location Overview: Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area. Location is approximately 273 yards from West Mamm Creek. Location is within close proximity to Rule 411.b Generalized External Buffer.**  
**Section/Township/Range: 22 7S93W**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N22W Pad**  
**Location # 324286**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N22W Pad**  
**Location # 324286**



**Photo # 7986 Erosion & transport of sediment/insufficient BMP's (NW corner of location)**



**Photo # 7988 Erosion & transport of sediment/insufficient BMP's (NW corner of location)**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N22W Pad**  
**Location # 324286**



**Photo # 7989 Erosion & transport of sediment/insufficient BMP's (NW corner of location)**



**Photo # 7990 Erosion & transport of sediment/insufficient BMP's (NW corner of location)**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N22W Pad**  
**Location # 324286**



**Photo # 7992 Erosion & transport of sediment/insufficient BMP's (NW corner of location)**



**Photo # 7993 Erosion & transport of sediment/insufficient BMP's (NW corner of location)**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N22W Pad**  
**Location # 324286**



**Photo # 7994 Erosion & transport of sediment/insufficient BMP's (NW corner of location)**



**Photo # 7995 Erosion & transport of sediment/insufficient BMP's (NW corner of location)**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N22W Pad**  
**Location # 324286**



**Photo # 7996 Erosion & transport of sediment/insufficient BMP's (NW corner of location)**



**Photo # 7997 Erosion & transport of sediment/insufficient BMP's (NW corner of location)**