

Inspection Photos
Location Name: CAERUS PICEANCE LLC K22W Pad
Location # 433706



Photo # 7949 From entrance to location



Photo # 7950 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC K22W Pad

Location # 433706



Photo # 7954 Location



Photo # 7955 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC K22W Pad
Location # 433706



Photo # 7956 Location



Photo # 7957 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC K22W Pad

Location # 433706



Photo # 7958 Location



Photo # 7959 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC K22W Pad
Location # 433706



Photo # 7960 Debris



Photo # 7964 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC K22W Pad

Location # 433706



Photo # 7971 Hole in liner/liner needs maintenance



Photo # 7972 Hole in liner/liner needs maintenance