

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2023

Submitted Date:

08/25/2023

Document Number:

712700576

FIELD INSPECTION FORMLoc ID 333768 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268715	WELL	PR	02/01/2020	CBM	067-08842	CHAPMAN A 2	PR
298806	WELL	PR	10/07/2008	CBM	067-09632	CHAPMAN A 4	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location			
Lease Road:			
Type	Access		
comment:	Locked gate, 2C40 key.		
Corrective Action	L	Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Present		
Corrective Action:		Date:	
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Pumpjack weight on ground. See Photo #6.		
Corrective Action:	Remove unused equipment per Rule 606, or return to service.	Date:	10/04/2023
Type	WEEDS		
Comment:	Access road is overgrown with Kochia. Weeds growing among separators. See Photos #4 & #5.		
Corrective Action:	Remove weeds along access road per Rule 606. Rule 610.k remove weeds and any other combustible material within 25' of fired equipment.	Date:	09/19/2023
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Metal mesh		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	And tank, and meterhouses, cattle panel.		

Corrective Action:			Date:		
Equipment:			corrective date		
Type: Ancillary equipment	# 2				
Comment: Wellhead					
Corrective Action:			Date:		
Type: Bird Protectors	# 2				
Comment:					
Corrective Action:			Date:		
Type: Flow Line	# 2				
Comment: 3" line from wellhead to separator.					
Corrective Action:			Date:		
Type: Ancillary equipment	# 1				
Comment: Telemetry					
Corrective Action:			Date:		
Type: Ancillary equipment	# 1				
Comment: Electrical box					
Corrective Action:			Date:		
Type: Prime Mover	# 1				
Comment: Electric motor					
Corrective Action:			Date:		
Type: Pump Jack	# 1				
Comment:					
Corrective Action:			Date:		
Type: Horizontal Heated Separator	# 2				
Comment:					
Corrective Action:			Date:		
Type: Bradenhead	# 2				
Comment: PVC access					
Corrective Action:			Date:		
Type: Gas Meter Run	# 2				
Comment: 3" line from separator to meterhouse. Calibration date 7/4/2023.					
Corrective Action:			Date:		
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:			Date:		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.183980,-107.799560	
Comment:						

Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Wells Served By Facilities Above						
API Number		API Number		AirsID		
067-09632						
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected FacilitiesFacility ID: 268715 Type: WELL API Number: 067-08842 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 05/30/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: Facility ID: 298806 Type: WELL API Number: 067-09632 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 05/30/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Ditches	Pass	Culverts	Pass			
Compaction	Pass	Gravel	Pass			
Culverts	Pass	Ditches	Pass			

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700581	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6240923