

Inspection Photos
Location Name: Guerrero 13, 14, 23, 33, 35-7
Location ID: 423389



Photo 1: TA Wellhead



Photo 2: TA Wellhead



Inspection Photos
Location Name: Guerrero 13, 14, 23, 33, 35-7
Location ID: 423389



Photo 3: TA Wellhead



Photo 4: TA Wellhead

Inspection Photos
Location Name: Guerrero 13, 14, 23, 33, 35-7
Location ID: 423389



Photo 5: TA Wellhead



Photo 6: Overgrown vegetation.

Inspection Photos
Location Name: Guerrero 13, 14, 23, 33, 35-7
Location ID: 423389



Photo 7: Overgrown vegetation on access road to wellheads.



Photo 8: Tank Battery Signs

Inspection Photos
Location Name: Guerrero 13, 14, 23, 33, 35-7
Location ID: 423389



Photo 9: Weeds



Photo 10: Over grown vegetation.

Inspection Photos
Location Name: Guerrero 13, 14, 23, 33, 35-7
Location ID: 423389



Photo 11: Weeds



Photo 12: Weeds

Inspection Photos
Location Name: Guerrero 13, 14, 23, 33, 35-7
Location ID: 423389



Energy & Carbon Management Commission
40.1475, -104.71484, 1506.3m, 312°
Sep 5, 2023 12:31:22

Photo 13: Weeds