

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNION ENERGY MINING DIV.-66S96W/33SWSE

Location ID: 334868

Date: 8/24/2023



North End of Location – Photo #06148



South End of Location – Photo #06150

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNION ENERGY MINING DIV.-66S96W/33SWSE

Location ID: 334868

Date: 8/24/2023



Wellheads – Photo #06149



Separators – Photo #06151

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNION ENERGY MINING DIV.-66S96W/33SWSE

Location ID: 334868

Date: 8/24/2023



Tank Battery – Photo #06152



Location Lacks Stabilization – Photo #06155

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNION ENERGY MINING DIV.-66S96W/33SWSE

Location ID: 334868

Date: 8/24/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #06153**



**Insufficient Erosion Control/Rill Erosion on Access Road –  
Photo #06154**