

Operator: EXTRACTION OIL & GAS INC
Location Name: BRERETON-61S69W 14SWSE
Loc ID: 321359
Inspection: 705000412



Exhibit A



Exhibit B

CA: Well (Brereton 2-14) has been plugged and abandoned. ECMC form 42 notice of start of plugging operations doc #403437490 received on 06/19/2023. ECMC flowline pre-abandonment notice doc #403390984 received on 05/02/2023; flowline AIP work has not been completed at time of inspection. Fenced excavation observed at the PA wellhead. Flowline riser (WH) at PA well observed at south end excavation (No OOSLAT in place); flowline riser at inlet to HHS connected to flowline manifold (No isolation/ OOSLAT). Facility/ battery services additional (SI) wells. Remediation work is in progress. Comply with ECMC Rules 1105.b. & 1105.c.

CA Resolution: Operator has reported and provided photo evidence that appropriate OOSLAT have been installed at the flowline riser (WH) and the flowline riser at the inlet to HHS connected to the flowline manifold to comply with Rules 1105.b. & 1105.c.