

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NESW

Location ID: 324117

Date: 8/24/2023



SW Corner of Location – Photo #06183



SE Corner of Location – Photo #06184

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NESW

Location ID: 324117

Date: 8/24/2023



NE Corner of Location – Photo #06185



Wellhead – Photo #06186

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NESW

Location ID: 324117

Date: 8/24/2023



Separator – Photo #06188

Tank Battery – Photo #06189

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NESW

Location ID: 324117

Date: 8/24/2023



**Location Lacks Stabilization – Photo #06187**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #06190**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NESW

Location ID: 324117

Date: 8/24/2023



Insufficient Erosion Controls/Rill Erosion on Access Road –  
Photo #06191



Insufficient Erosion Controls/Rill Erosion on Access Road –  
Photo #06192