

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2023

Submitted Date:

09/06/2023

Document Number:

708300828

FIELD INSPECTION FORM

 Loc ID 334862 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:
 OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635
Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211344	WELL	PR	10/29/1997	GW	045-07104	FEDERAL GM 24-33	PR
260220	WELL	PR	06/26/2002	GW	045-07833	FEDERAL GM 14-33	PR
286917	WELL	PR	02/13/2008	GW	045-12829	FEDERAL GM 424-33	PR
286918	WELL	PR	02/13/2008	GW	045-12828	FEDERAL GM324-33	PR
286919	WELL	PR	01/29/2009	GW	045-12827	FEDERAL GM 314-33	PR

General Comment:[COGCC Inspection Report Summary](#)

On 8/24/2023 at approximately 12:25, Compliance Inspector Matthew Morris conducted a follow-up inspection at TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/33SESW at Location ID #334862 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Delay in report submission due to technical issues. Any corrective action dates will be in effect from date of submission, not date of inspection.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911/(970) 285-9377		
Corrective Action:		Date:	_____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Livestock fencing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock fencing		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Livestock fencing		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 5		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 5		
Comment:	All bradenhead valves are accessible.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	500 gal
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities				
Facility ID: <u>211344</u>	Type: <u>WELL</u>	API Number: <u>045-07104</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment:				
Corrective Action:			Date:	
Facility ID: <u>260220</u>	Type: <u>WELL</u>	API Number: <u>045-07833</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment:				
Corrective Action:			Date:	
Facility ID: <u>286917</u>	Type: <u>WELL</u>	API Number: <u>045-12829</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment:				
Corrective Action:			Date:	
Facility ID: <u>286918</u>	Type: <u>WELL</u>	API Number: <u>045-12828</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment:				
Corrective Action:			Date:	
Facility ID: <u>286919</u>	Type: <u>WELL</u>	API Number: <u>045-12827</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment:				
Corrective Action:			Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail					Insufficient vehicle tracking BMPs
		Ditches				
		Rip Rap				
Seeding						
		Other	Fail			Insufficient erosion controls
Berms						
		Retention Ponds				
		Berms				
		Gravel				
		Check Dams				
		Compaction	Fail			Access road lacks stabilization
		Sediment Traps				
Gravel	Fail					Insufficient gravel
		Culverts				
Ditches						
Compaction	Fail					Location lacks stabilization

Comment: 1) Location surface lacks stabilization with insufficient vehicle tracking BMPs in place to minimize transportation of sediment.
2) Insufficient erosion control on access road; rill erosion cutting through access road.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002.

Date: 09/21/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708300851	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6242098