

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2023

Submitted Date:

08/31/2023

Document Number:

704900020

## FIELD INSPECTION FORM

Loc ID 325573 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10254Name of Operator: RED MESA HOLDINGS/O&G LLCAddress: 5619 DTC PARKWAY - STE 800City: GREENWOOD State: CO Zip: 80111**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****General Comment:**

On July 19, 2023 ECMC OWP West EPS Jim Hughes conducted a field inspection of the Red Mesa Holdings Herrera #4. For the most recent field inspection report of this facility, please refer to document #685304184.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt road extending beyond driveway of nearby residence.		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Metal sign mounted to guard fencing of pumping unit.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	COGCC emergency contact information sticker on well head sign.		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog wire fence panels and "T" posts.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Guard fencing		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Electric supply panel.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			

Inspector Name: Hughes, Jim

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

COGCC Comments		
Comment	User	Date
On July 19, 2023 ECMC OWP West EPS Jim Hughes conducted a field inspection of the Red Mesa Holdings Herrera #4. For the most recent field inspection report of this facility, please refer to document #685304184. This site visit was performed with Cottonwood Consulting representatives to assess current conditions at this facility prior to plugging and abandonment.	hughesjo	08/31/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
704900021	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6242265">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6242265</a>