

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/19/2023

Submitted Date:

08/31/2023

Document Number:

704900024

FIELD INSPECTION FORM

Loc ID 325542 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10254
Name of Operator: RED MESA HOLDINGS/O&G LLC
Address: 5619 DTC PARKWAY - STE 800
City: GREENWOOD State: CO Zip: 80111

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214977	WELL	PR	01/01/2011	OW	067-06582	TURNER (OWP) 3	EI

General Comment:

On July 19, 2023 ECMC OWP West EPS Jim Hughes conducted a field inspection of the Red Mesa Holdings Turner #3. For the most recent field inspection report of this facility, please refer to document #685305358.

Location

Lease Road:			
	Type Access		
comment:	Dirt two track road is accessible. Does not appear to be maintained.		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type WELLHEAD		
Comment:	Metal sign mounted to guard fencing of pumping unit.		
Corrective Action:			Date:

Emergency Contact Number:			
	Comment: COGCC contact information sticker on well sign.		
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type TANK BATTERY		
Comment:	Steel post and hog wire fencing.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment: Electric motor			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment: Electrical supply equipment.			
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		37.080968,-108.120192
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity) 210 bbl					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected FacilitiesFacility ID: 214977 Type: WELL API Number: 067-06582 Status: PR Insp. Status: EI**COGCC Comments**

Comment	User	Date
On July 19, 2023 ECMC OWP West EPS Jim Hughes conducted a field inspection of the Red Mesa Holdings Turner #3. For the most recent field inspection report of this facility, please refer to document #685305358. This site visit was performed with Cottonwood Consulting representatives to assess current conditions at this facility prior to plugging and abandonment.	hughesjo	08/31/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
704900025	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6242267