

Federal 11-90-24 #1 —API—051-06057

Inspection Doc 708300782 —8/14/2023

CA #1 of 3—Fan shroud stored near pump jack.—Removed 8/17/2023





Federal 11-90-24 #1 —API—051-06057

Inspection Doc 708300782 —8/14/2023

CA #2 of 3—Bradenhead valve not accessible

Exposed BH Buried valve, confirmed open 8/24/23.

Cellar installed over buried BH valve 8/31/23.





Federal 11-90-24 #1 —API—051-06057

Comment—Missing label on Antifreeze tank.—New label applied 8/24/23

