

## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 22-14 Pad

Location # 335853



Photo # 8220 From entrance to location



Photo # 8221 From entrance to location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 22-14 Pad

Location # 335853



Photo # 8222 From entrance to location



Photo # 8223 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 22-14 Pad

Location # 335853



Photo # 8224 Location



Photo # 8225 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 22-14 Pad

Location # 335853



Photo # 8226 Location



Photo # 8227 RWF 413-14 wellhead sign illegible

## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 22-14 Pad

Location # 335853



Photo # 8230 Stained soils & gravel near wellheads



Photo # 8241 Stained soils & gravel near wellheads

## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 22-14 Pad

Location # 335853



Photo # 8243 Stained soils & gravel near wellheads



Photo # 8213 Battery sign weathered & illegible