

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/23/2023

Submitted Date:

08/23/2023

Document Number:

679606137

FIELD INSPECTION FORM

Loc ID 430616 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430615	WELL	SI	04/01/2021	OW	123-36212	BYDALEK 28C-20HZ	TA
430618	WELL	SI	02/01/2021	OW	123-36214	BYDALEK 4N-20HZ	TA
430620	WELL	SI	02/01/2021	OW	123-36216	BYDALEK 28N-20HZ	TA
430622	WELL	SI	10/01/2020	OW	123-36217	BYDALEK 3N-20HZ	TA
430624	WELL	PR	09/12/2013	OW	123-36219	BYDALEK 29C-20HZ	PR
430626	WELL	PR	02/01/2020	OW	123-36220	BYDALEK 29N-20HZ	PR
430629	WELL	PR	09/12/2013	OW	123-36223	BYDALEK 30C-20HZ	TA

General Comment:

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	unused/disconnected equipment on location. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	10/07/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	SEPARATOR		
Comment:	wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	iron		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	iron		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 7		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 5		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		,		
Comment:							
Corrective Action:						Date:	
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity) 210 BBLS							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:		Shares containment with other tanks.					
Corrective Action:						Date:	
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
Flaring:							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities

Facility ID: 430615 Type: WELL API Number: 123-36212 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment:

Corrective Action: Date:

Facility ID: 430618 Type: WELL API Number: 123-36214 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment:

Corrective Action: Date:

Facility ID: 430620 Type: WELL API Number: 123-36216 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment:

Corrective Action: Date:

Facility ID: 430622 Type: WELL API Number: 123-36217 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment:

Corrective Action: Date:

Facility ID: 430624 Type: WELL API Number: 123-36219 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action: Date:

Facility ID: 430626 Type: WELL API Number: 123-36220 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action: Date:

Facility ID: 430629 Type: WELL API Number: 123-36223 Status: PR Insp. Status: TA

Producing Well

Comment:

Corrective Action: Date:

Idle Well

Purpose: Shut In

Temporarily Abandoned

Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary **Weather Conditions: sunny, dry ground On Wednesday, August 23, 2023 at approximately 12:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at BYDALEK 28C-20HZ (Kerr McGee Oil & Gas Onshore), at location #: 430616 in WELD COUNTY Colorado. While there, I observed a shut in facility. During this inspection the following possible compliance issues were observed: 1. It appears to be unused/disconnected equipment near wellheads. Reconnect or remove from location per Rule 606. (Corrective Action Date: October 7, 2023) See attached photo #3-8. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	08/23/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679606138	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6244043