

Inspection Photos

API: 099-06063

Operator: RENEGADE OIL & GAS COMPANY

Inspection Date: 9/6/2023



Inspection Photos



Photo 1. Facing northeast toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 099-06063 | Date: 9/6/2023

Inspection Photos



Photo 2. There is oily soils that have been dumped on the ground which appears to have been dug up at the tank battery. This has caused additional contamination. E&P waste was not properly disposed.



Inspection Photos



Photo 3. Facing toward the tank battery. There is oil stained soil at the pipe outlet and at the base of the tanks.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. The oil stained soils have been dug up with a shovel oily soils still remain and need to be fully excavated and properly disposed. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 099-06063 | Date: 9/6/2023

Inspection Photos



Photo 5. There is oil staining that overtopped the open top tank. There is oil inside the tank and the tank is mislabeled as produced water. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 099-06063 | Date: 9/6/2023

Inspection Photos



Photo 6. The netting on the open top tank is still insufficient to prevent wildlife entry. Previous corrective action was not completed.



Inspection Photos



Photo 7. The fence at the northwest corner of the tank battery is in disrepair..



Inspection Photos



Photo 8. Facing southwest toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 099-06063 | Date: 9/6/2023