

Inspection Photos

API: 099-06909

Operator: RENEGADE OIL & GAS COMPANY

Inspection Date: 9/6/2023



Inspection Photos



Photo 1. Facing northeast toward the offsite tank battery there is no sign posted at the tank battery which is off site from the well. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 099-06909 | Date: 9/6/2023

Inspection Photos



Photo 2. Facing toward the tank which is labeled as water. It appears crude oil has leaked out from the top. Additionally there is no secondary containment around the tank. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 099-06909 | Date: 9/6/2023

Inspection Photos



Photo 3. Facing toward the tank battery. There is oil stained soil at the pipe outlet and at the base of the tanks. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 099-06909 | Date: 9/6/2023

Inspection Photos



Photo 4. There is well sign posted at the wellhead. The well is a distance away from the tank battery and an addition sign should be posted at the tank battery.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 099-06909 | Date: 9/6/2023