

Inspection Photos

API: 099-06059

Operator: RENEGADE OIL & GAS COMPANY

Inspection Date: 9/6/2023



Inspection Photos



Photo 1. Facing southeast at the abandoned wellsite. There is an abandoned pipe riser that still remains and must be removed. Pipe riser is interfering with crop production.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 099-06059 | Date: 9/6/2023

Inspection Photos



Photo 2. Abandoned capped pipe riser needs to be removed.

