

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/06/2023

Submitted Date:

09/07/2023

Document Number:

713600203

FIELD INSPECTION FORM

Loc ID 314177 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #225
City: AURORA State: CO Zip: 80016

Findings:

- 5 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|-------|---------------------------|---------|
| Sanchez, Chris | | chris.sanchez@state.co.us | |
| INGVE EDWARD | | ed@renegadeoilandgas.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|--------------|--------|-------------|------------|-----------|------------------------|-------------|
| 227737 | WELL | PR | 12/01/2021 | GW | 099-06063 | IDLER C 1 | RI |
| 447057 | TANK BATTERY | AC | 07/29/2016 | | - | IDLER C-622S47W 29SWSW | RI |

General Comment:

On 9/6/2023, Ryan Costa conducted a follow up location inspection. See attached photos and additional details within this report.

Previous corrective actions have not been completed and additional issues have been observed. Operator is directed to perform corrective actions outlined on this inspection report immediately.

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---|-------|------------|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | The open top tank labeling is inaccurately posted as produced water and there is crude oil in the tank. Previous corrective action was not completed. | | |
| Corrective Action: | Install sign to comply with Rule 605.h. and accurately show contents in the tank. | Date: | 07/11/2023 |

Emergency Contact Number:

| | | | |
|--------------------|----------------------|-------|----------------------|
| Comment: | <input type="text"/> | Date: | <input type="text"/> |
| Corrective Action: | <input type="text"/> | | |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|--------------------|---|--------|--|-------|------------|
| Crude Oil | Tank | | | | |
| Comment: | There is oil stained soils at the two tanks and at the pipe outlet. It appears part of the stained soils were dug up by the tank and dumped on the ground which is causing further contamination of soils. E&P waste must be properly cleaned up and disposed per Rule 905. Previous corrective action was not completed. | | | | |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 912.a. | | | Date: | 07/12/2023 |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|--|-------|------------|
| Type | TANK BATTERY | | |
| Comment: | The fence around the tank battery is in disrepair. | | |
| Corrective Action: | Comply with the fencing requirements per the 1002a rules | Date: | 09/06/2023 |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS | |
|--------------------|---|----------|----------|---------|--------|------------|
| CRUDE OIL | 1 | | Open Top | | | |
| Comment: | The netting on the open top tank is insufficient to prevent wildlife entry. Previous corrective action was not completed. | | | | | |
| Corrective Action: | Install or repair wildlife protection equipment. | | | | Date: | 07/11/2023 |

Paint

| | |
|------------------|----------------------|
| Condition | <input type="text"/> |
| Other (Content) | <input type="text"/> |
| Other (Capacity) | <input type="text"/> |
| Other (Type) | <input type="text"/> |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|----------|----------------------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | <input type="text"/> | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 713600204 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6244435 |