

Inspection Photos

API: 011-06036

Operator: OXY USA INC

Inspection Date: 9/6/2023



Inspection Photos



Photo 1. Facing southwest at the location. Perennial vegetation has re-established at the location.



Inspection Photos



Photo 2. Facing southeast at the location. Perennial vegetation has re-established at the location. There is bunched up netting from the straw blanket that needs to be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 011-06036 | Date: 9/6/2023

Inspection Photos



Photo 3. Southwest corner of the location. There is bunched up netting from the straw blanket that needs to be removed.



Inspection Photos



Photo 4. Facing southwest at the disturbed location.



Photo 5. Facing northeast at the disturbed location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 6. Facing northwest at the reference area.



Photo 7. Facing southeast at the reference area. .



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

[illegible]