

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 312598

Date: 9/6/2023



North Entrance to Location – Photo #06238



SE Corner of Location – Photo #06242

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 312598

Date: 9/6/2023



SW Corner of Location – Photo #06243



Wellhead/Weeds – Photo #06239

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 312598

Date: 9/6/2023



Separator/Gas Meter/Weeds – Photo #06240



Tank Battery/Weeds – Photo #06241

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 312598

Date: 9/6/2023



Trash/Debris – Photo #06246



Trash/Debris – Photo #06247

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 312598

Date: 9/6/2023



Location Lacks Stabilization – Photo #06248



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #06249

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE

Location ID: 312598

Date: 9/6/2023



**Insufficient Erosion Control/Rill Erosion on Access Road –
Photo #06250**