

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/06/2023

Submitted Date:

09/07/2023

Document Number:

708300858

**FIELD INSPECTION FORM**Loc ID 312598 Inspector Name: Morris, Matthew On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10770

Name of Operator: VISION ENERGY LLC

Address: P O BOX 370

City: IGNACIO State: CO Zip: 81137

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

15 Number of Comments

7 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
ENERGY, VISION		mco@visionenergy.biz	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221992	WELL	SI	04/01/2010	CBM	077-08594	SOUTH SHALE RIDGE 1-14	SI

**General Comment:****COGCC Inspection Report Summary**

On 9/6/2023 at approximately 10:05, Compliance Inspector Matthew Morris conducted a follow-up inspection at VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/14NENE at Location ID #312598 in Mesa County, Colorado.

Corrective actions from FIR #708300312 have not been completed.

During the inspection, the following compliance issues were observed:

- 1) Weeds/undesirable plant species present throughout production area
- 2) Tank battery berm has inadequate permeability due to weed growth
- 3) Trash and debris on location which includes a fire pit and burned trash
- 4) Inaccurate operator information on battery sign and wellhead sign
- 5) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Wellhead sign has inaccurate operator information.		
Corrective Action:	Install wellhead sign with correct information to comply with Rule 605.d.	Date:	05/18/2023
Type	BATTERY		
Comment:	Battery sign has inaccurate operator information.		
Corrective Action:	Install battery sign with correct information to comply with Rule 605.h.	Date:	05/18/2023

**Emergency Contact Number:**

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Burned trash present on location.		
Corrective Action:	Remove trash from location to comply with Rule 606.	Date:	04/25/2023
Type	WEEDS		
Comment:	Weeds and undesirable plant species present throughout production area.		
Corrective Action:	Remove weeds and undesirable plant species to comply with Rule 606.	Date:	04/25/2023
Type	DEBRIS		
Comment:	Fire pit and other debris present on location.		
Corrective Action:	Remove debris from location to comply with Rule 606.	Date:	04/25/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	Containment is not sufficiently impervious to contain spilled or released materials due to weed growth.				
Corrective Action:	Repair berm and remove weeds to comply with Rule 603.o.				Date: 05/18/2023

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	221992	Type:	WELL	API Number:	077-08594	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: Last produced April 2010. Last MIT performed April 2022.									
Corrective Action: _____ Date: _____									

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail					Insufficient vehicle tracking BMPs
Rip Rap						
Waddles	Fail					BMP degraded and insufficient
		Ditches				
		Other	Fail			Insufficient vehicle tracking BMPs
Compaction	Fail					Location lacks stabilization
		Compaction	Fail			Access road lacks stabilization

Comment: 1) Erosion cutting under waddles allowing transport of sediment from location  
 2) Inadequate tracking BMP on lease road to/from location entrance  
 3) Sediment transport from lease road has encroached onto nearby vegetation

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002.

Date: 09/22/2023

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708300859	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6245065">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6245065</a>