

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/18/2023

Submitted Date:

08/24/2023

Document Number:

694500590

**FIELD INSPECTION FORM**Loc ID 324702 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 34162

Name of Operator: GILS HOT OIL SERVICE

Address: P O BOX 418

City: STRASBURG State: CO Zip: 80136

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Paine, Gilbert	303-709-0148	cherokeeequipment@hotmail.com	
Ramsey, Scott		scott.ramsey@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212480	WELL	PR	05/01/2021	OW	057-06374	STATE 3-X	EI

**General Comment:**

Any Corrective Actions from previous Inspections that have not been addressed are still applicable. On 8/3/23, C-ECMC staff, Kris Neidel was on location to inspect the State 3X Well. The well was SI at the time of inspection. The following was observed. Pumping unit on a steel base. Well has a 4 wire fence. There is a 200bbl tank that has a dirt berm secondary containment. It appears that this is the Poly flowline that is coming from the 12-1 well. There is no Sign identifying this tank as related to the 12-1 well. There is an old pulling unit at the wellhead. The rig is laid down on the truck. There is other workover debris and trash at the well. There is a Warning Letter, doc 2193064 in the well file for a lack of MIT on this TA well. To date (8/24/2023) there is no record of this well being MITd. See attached Photos.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	DEBRIS		
Comment:	There is an old pulling unit at the wellhead. The rig is laid down on the truck. There is other workover debris and trash at the well. There is trash.		
Corrective Action:	Remove all stored equipment from location		Date: 06/23/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	212480	Type:	WELL	API Number:	057-06374	Status:	PR	Insp. Status:	EI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403518802	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6239934">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6239934</a>
694500591	photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6239928">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6239928</a>