

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/31/2023

Submitted Date:

09/08/2023

Document Number:

709100101

**FIELD INSPECTION FORM**Loc ID 303242 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Krystal Heibel	303-817-5217	krystal.heibel@state.co.us	
Jones, Greg	970-332-3585	greg.jones@ownresources.com	
Dolezal, Pat		pat.dolezal@ownresources.com	Inspections
SCHNEIDER, ED		ed.schneider@ownresources.com	Principal Agent

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
107851	PIT	AC			-	SALVADOR 2-5	EI
252736	WELL	PR	02/09/1988	GW	125-06612	SALVADOR 2-5	EI

**General Comment:**

This is an environmental progress inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site conditions.

On Thursday 08/31/2023, an environmental inspection was performed for the Salvador 2-5 location and pit. Operator personnel was not present during time of inspection. Photos attached to document site conditions.

Operator Name: OWN RESOURCES OPERATING LLC (Op# 10699)

Facility Name: SALVADOR-64N46W 5NWNE

Well API: 05-125-06612

SALVADOR 2-5 Pit, Location ID: 107851

Location ID: 303242

County: Yuma County, Colorado

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Cropland		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	SIGN LAYING ON GROUND - SIGN REQUIRED TO BE VISIBLE - RESTORE SIGNAGE. This comment was documented in the 12-08-2022 Inspection Report (Doc# 701602788).		
Corrective Action:	Install sign to comply with Rule 605.d. and 605.g.	Date:	11/09/2023

Emergency Contact Number:

Comment: SIGN LAYING ON GROUND - SIGN REQUIRED TO BE VISIBLE - RESTORE SIGNAGE. This comment was also documented in the 12-08-2022 Inspection Report (Doc# 701602788).

Corrective Action: Install sign to comply with Rule 605.d. and 605.g.

Date: 11/09/2023

**Good Housekeeping:**

Type	OTHER		
Comment:	Burrows observed near wellhead.		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	CATTLE HAVE KNOCKED FENCE DOWN - SEE ATTACHMENT PHOTO. This comment was also documented in the 12-08-2022 Inspection Report (Doc# 701602788).		
Corrective Action:	Comply with Rule 1002.a.(3)	Date:	09/23/2023

<b>Equipment:</b>			corrective date
Type: Other	#		
Comment:	Wellhead valve not sealed, plugged, or capped.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	09/23/2023

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	107851	Type:	PIT	API Number: -	Status:	AC	Insp. Status:	EI	
Facility ID:	252736	Type:	WELL	API Number:	125-06612	Status:	PR	Insp. Status:	EI

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: \_\_\_\_\_ Lined: NO Pit ID: 107851 Lat: 40.349645 Long: -102.535151

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type:

Liner Condition:

Comment: Pit not observed in the location provided.

Corrective Action: Operator shall update the pit location (including accurate latitude and longitude) within an updated Form 15.

Date: 10/09/2023**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action:

Date:

**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective Action:

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100102	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6245477">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6245477</a>