

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/07/2023

Submitted Date:

09/08/2023

Document Number:

712700628

FIELD INSPECTION FORM
 Loc ID 325650 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 96735

Name of Operator: WILLIFORD RESOURCES LLC

Address: 6506 S LEWIS AVE STE 102

City: TULSA State: OK Zip: 74136

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Williford, Hearne		hwilli@swbell.net	All SW Inspections
Stevens, Glenn		glennstevens@centurylink.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215167	WELL	PR	04/01/2023	OW	067-06772	ANGELINA 6	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a follow up field inspection to verify completion of corrective actions identified in FIR Document #695108252 submitted 5/23/2023.

Equipment inventory listed on previous inspection, no change in equipment.

Location

Lease Road:			
Type	Access		
comment:	Dirt two-track		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Metal sign posted at wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on wellhead sign.		
Corrective Action:		Date:	

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Observed three hoses on the ground at the north side of the pumpjack fencing. This corrective action was identified in FIR Doc.#695108252, and has not been completed. Corrective action date is retained.		
Corrective Action:	Remove unused equipment per Rule 606.	Date:	06/05/2023
Type	OTHER		
Comment:	Observed impacted material on ground at wellhead. This corrective action was identified in FIR Doc.#695108252, and has not been completed. Corrective action date has been retained.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes, per Rule 1002.(2).D.	Date:	06/05/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	215167	Type:	WELL	API Number:	067-06772	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	11/01/2022	Annual Brhd Completed?	No						
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Ditches	Pass			

Comment: [Tear drop around production equipment.](#)
[No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700634	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6245895