

Final Reclamation and Stormwater Inspection

Date: 09/05/2023

Operator: SCHNEIDER ENERGY SERVICES INC - 76840

Location ID: 395432

Inspection Document #: 708200538

Morgan County, CO

NESW Section 31 T6N R58W

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: Don 1
Location ID: 395432



Photo 1. Taken from the access road. Evidence of CO List B Noxious weed (scotch thistle) observed within lease road

Inspection Photos
Location Name: Don 1
Location ID: 395432



Photo 2. Close up of Scotch thistle; see comments in Photo 1.

Inspection Photos
Location Name: Don 1
Location ID: 395432



Photo 3. The former access road does not appear to have been reclaimed with evidence of contouring issues. Also pictured, Scotch thistle.

Inspection Photos
Location Name: Don 1
Location ID: 395432



Photo 4. Road base/gravel remains throughout portions of the location and will need to be removed.

Inspection Photos
Location Name: Don 1
Location ID: 395432



Photo 5. Area south of the access road. Undesirable vegetation (e.g. russian thistle and kochia; and CO List C Noxious weed- cheatgrass) was observed to be growing throughout.

Inspection Photos
Location Name: Don 1
Location ID: 395432



Photo 6. Close up photo of Colorado List C Noxious weed- Field bindweed.

Inspection Photos
Location Name: Don 1
Location ID: 395432



Photo 7. Area north of access road; Some desirable perennial vegetation was observed within the former pit area as well as areas of non-uniform vegetative cover and road base/gravel were evident.

Inspection Photos
Location Name: Don 1
Location ID: 395432



Photo 8. Reference area photo taken south of location.