

# Final Reclamation and Stormwater Inspection

Date: 09/05/2023

Operator: SCHNEIDER ENERGY SERVICES INC- 76840

Location ID: 313840

Inspection Document #: 708200539

Morgan County, CO

SENE Section 4 T5N R58W

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Patterson 1  
Location ID: 313840



**Photo 1.** The access road entrance requires additional reclamation activities as bare/exposed soils and undesirable vegetation were evident during this inspection.

Inspection Photos  
Location Name: Patterson 1  
Location ID: 313840



**Photo 2.** Colorado List B Noxious Weed- Scotch Thistle observed to be growing along the former access road; this weed species requires active and immediate management to prevent spread onto adjacent lands.

Inspection Photos  
Location Name: Patterson 1  
Location ID: 313840



**Photo 4.** The former access road requires additional contouring and grading; cut banks illustrated.

Inspection Photos  
Location Name: Patterson 1  
Location ID: 313840



**Photo 4.** Access road south of the location; see comments in Photo 3.

Inspection Photos  
Location Name: Patterson 1  
Location ID: 313840



**Photo 5.** The former tank battery area is not progressing towards Rule 1004 regulations and standards as illustrated by non-uniform vegetation cover resulting areas of bare/exposed soils.

Inspection Photos  
Location Name: Patterson 1  
Location ID: 313840



**Photo 6.** Taken from the northern portion of the location; see comments in Photo 5.

Inspection Photos  
Location Name: Patterson 1  
Location ID: 313840



**Photo 7.** Taken from the northern portion of the location. The cut banks are predominantly bare/exposed soils and require additional contouring within the former wellhead area.

Inspection Photos  
Location Name: Patterson 1  
Location ID: 313840



**Photo 8.** Taken west of the former wellhead. Non-uniform vegetative cover and the presence of undesirable vegetation (e.g. russian thistle) pictured.

Inspection Photos  
Location Name: Patterson 1  
Location ID: 313840



**Photo 9.** Taken near the former pit location. See comments in Photo 8.

Inspection Photos  
Location Name: Patterson 1  
Location ID: 313840



**Photo 10.** Facing towards the former pit location; see comments in Photo 8.

Inspection Photos  
Location Name: Patterson 1  
Location ID: 313840



**Photo 11.** Taken from the center portion of the location. Photo illustrates additional recontouring activities that are required around the former wellhead location.

Inspection Photos  
Location Name: Patterson 1  
Location ID: 313840



**Photo 12.** Debris left on location (e.g. metal pipe and road base/gravel).