

Storm Water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH 128 Pad
Location # 322493



**Location Overview: Location is within High Priority/Density
Habitat areas & Bald Eagle Roost site.**
Section/Township/Range: 23 6S94W

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH 128 Pad
Location # 322493



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH 128 Pad
Location # 322493



**Photo # 8590 Lack of stabilization/compaction on spur road
& location**



Photo # 8599 Lack of stabilization/compaction on location

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH 128 Pad
Location # 322493



Photo # 8603 Lack of stabilization/compaction on location



Photo # 8604 Lack of stabilization/compaction on spur road & location

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH 128 Pad
Location # 322493



Photo # 8605 Lack of stabilization/compaction on spur road



Photo # 8606 Lack of stabilization/compaction on spur road

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH 128 Pad
Location # 322493



Photo # 8607 Lack of stabilization/compaction on spur road



Photo # 8608 Lack of stabilization/compaction on spur road

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC CLOUGH 128 Pad
Location # 322493



Photo # 8609 Lack of stabilization/compaction on spur road



Photo # 8610 Lack of stabilization/compaction on spur road