

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/21/2023

Submitted Date:

08/21/2023

Document Number:

713300023

FIELD INSPECTION FORMLoc ID 335589 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	ALL INSPECTIONS
Silver, Randy		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241615	WELL	SI	01/01/2022	GW	123-09404	STIEBER GEORGE B 1	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	concrete support pad for pumping unit		
Corrective Action:	Comply with Rule 606	Date:	09/23/2023
Type	WEEDS		
Comment:	overgrown vegetation		
Corrective Action:	Comply with Rule 606	Date:	09/23/2023

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 241615 Type: WELL API Number: 123-09404 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: PRODUCTION RECORDSComment: at time of inspection appeared all flow lines disconnected from wellhead, unable to produceCorrective Action: Date: **BradenHead**Date of Last Brhd Test: 09/22/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Friday, 8-18-23 at approximately 10:00, I, Inspector Michael Kester, conducted an on-site inspection.</p> <p>Location: Stieber George B 1</p> <p>Operator: KPK</p> <p>API#: 123-09404</p> <p>County: Weld</p> <p>While there, I observed TA in well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>weeds: rule 606. See corrective action date 9-23-2023 attached photos #1,2,3,& 4</p> <p>Unused equipment: rule 606. corrective action date of 9-23-2023 See attached photos # 3 & 4</p> <p>Weather conditions: dry and clear</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of inspection report.</p>	kesterm	08/21/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300024	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247232