


Storm Water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC CLOUGH 27-11-6S-94W Pad
Location ID: 430758



Location Overview: Location is within High Priority Habitat area & Bald Eagle Nest & Roost sites & within close proximity to NSO/Density Habitat areas.

Section/Township/Range: 27 6S94W

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC CLOUGH 27-11-6S-94W Pad
Location ID: 430758



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.



Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC CLOUGH 27-11-6S-94W Pad
Location ID: 430758



Photo # 8712 Lack of stabilization/compaction on location



Photo # 8715 Lack of stabilization/compaction on location

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC CLOUGH 27-11-6S-94W Pad
Location ID: 430758



Photo # 8717 Lack of stabilization/compaction on location



Photo # 8722 Lack of stabilization/compaction on location

Storm water Management and Erosion control
Location Name: MUSTANG RESOURCES LLC CLOUGH 27-11-6S-94W Pad
Location ID: 430758



Photo # 8723 Lack of stabilization/compaction on location



Photo # 8725 Lack of stabilization/compaction on location