

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/06/2023

Submitted Date:

09/11/2023

Document Number:

708300862

FIELD INSPECTION FORM

Loc ID: 334269 Inspector Name: Morris, Matthew On-Site Inspection: 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10770
Name of Operator: VISION ENERGY LLC
Address: P O BOX 370
City: IGNACIO State: CO Zip: 81137

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 16 Number of Comments
- 9 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
ENERGY, VISION		mco@visionenergy.biz	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210984	WELL	SI	05/01/1996	CBM	045-06742	SOUTH SHALE RIDGE 1-8	SI
266868	WELL	SI	11/01/2007	CBM	045-09186	SOUTH SHALE RIDGE 1-8H	SI

General Comment:

[COGCC Inspection Report Summary](#)

On 9/6/2023 at approximately 10:20, Compliance Inspector Matthew Morris conducted a follow-up inspection at VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE at Location ID #334269 in Garfield County, Colorado.

Corrective actions from FIR #708300562 have not been completed. These corrective actions remain in effect.

During the inspection, the following compliance issues were observed:

- 1) Weeds on location have encroached on all production equipment
- 2) Unused equipment stored on location
- 3) No tank battery sign
- 4) Wellhead signs and tank labels contain inaccurate information
- 5) Weeds have compromised permeability of tank battery berms
- 6) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, and/or Wildlife Management area.

Delay in report submission due to technical issues. Any corrective action dates will be in effect from date of submission, not date of inspection.

Location

Overall Good:

Signs/Marker:		
Type	BATTERY	
Comment:	No tank battery sign.	
Corrective Action:	Install sign to comply with Rule 605.e.	Date: <u>04/13/2023</u>
Type	WELLHEAD	
Comment:	Inaccurate information on wellhead signs.	
Corrective Action:	Install sign to comply with Rule 605.d.	Date: <u>04/13/2023</u>
Type	TANK LABELS/PLACARDS	
Comment:	Inaccurate information on labels/placards.	
Corrective Action:	Install labels/placards to comply with Rule 605.h.	Date: <u>04/13/2023</u>

Emergency Contact Number:		
Comment:	<u>911/(970) 858-8550</u>	
Corrective Action:		Date: _____

Good Housekeeping:		
Type	UNUSED EQUIPMENT	
Comment:	Unused equipment stored on location.	
Corrective Action:	Remove unused equipment to comply with Rule 606	Date: <u>03/28/2023</u>
Type	OTHER	
Comment:	Stained soil on location near wellheads.	
Corrective Action:	Control and contain spills/releases and clean soil per Rule 912.a.	Date: <u>10/11/2023</u>
Type	WEEDS	
Comment:	Weeds have encroached entire production area.	
Corrective Action:	Remove weeds from location to comply with Rule 606.	Date: <u>03/20/2023</u>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 2		

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Weeds have compromised permeability and capacity of berm.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).			Date: 04/02/2023

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	Open Top		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Weeds have compromised permeability and capacity of berm.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).			Date: 04/02/2023

Venting:

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 210984 Type: WELL API Number: 045-06742 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last produced April 2010. Last MIT performed September 2021.

Corrective Action: _____ Date: _____

Facility ID: 266868 Type: WELL API Number: 045-09186 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last produced April 2010. Last MIT performed September 2021.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Other	Fail			Insufficient vehicle tracking BMPs
		Compaction	Fail			Access road lacks stabilization
Waddles	Fail					BMP degraded and insufficient
Rip Rap						
Sediment Traps						
Berms						
Ditches						

Comment: 1) Access road lacks stabilization with insufficient vehicle tracking BMPs in place to minimize transportation of sediment.
2) Waddles on west side of pad are degraded and insufficient.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to comply with Rule 1002.

Date: 03/20/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708300863	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247706