

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/28/2023

Submitted Date:

08/28/2023

Document Number:

712700586

FIELD INSPECTION FORMLoc ID 311995 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

21 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
, General		sjninspections@ikavenergy.co m	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215272	WELL	PR	09/01/2019	CBM	067-06877	FRANCIS WHITE A 1	PR
293294	WELL	PR	11/05/2007	CBM	067-09419	FRANCIS WHITE A 3	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location

Lease Road:			
Type	Access		
comment:	Locked gate, 2C40 key.		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not posted at oil and gas location.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	09/28/2023

Emergency Contact Number:

Comment: Wellhead sign not posted. No 24 hour emergency contact number posted.

Corrective Action: Install sign to comply with Rule 605.a.

Date: 10/04/2023

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	On three sides, T-post and barbed wire.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Above ground valve, pipe fence.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panel enclosure around separators, tank, meterhouse, and telemetry.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 2		
Comment:	Housed together		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Telemetry		
Corrective Action:		Date:	

Type: Gas Meter Run	# 2	
Comment:	3" lines from separator to meterhouse. Calibration date 6/1/2023.	
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:	One unmarked guy anchor.	
Corrective Action:	Mark guy anchor per Rule 1003, or remove if not serviceable or not needed for ongoing operations.	Date: 09/11/2023
Type: Ancillary equipment	# 2	
Comment:	Wellhead	
Corrective Action:		Date:
Type: Flow Line	# 4	
Comment:	2-3" lines from wellhead to separator. 2-1" lines from separator to prime mover.	
Corrective Action:		Date:
Type: Pump Jack	# 2	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 2	
Comment:	Natural gas motor	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 2	
Comment:	PVC access	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.158790,-10.809290
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

<u>Wells Served By Facilities Above</u>		<u>AirsID</u>	
API Number		API Number	AirsID
067-09419			
<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 215272 Type: WELL API Number: 067-06877 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 07/21/2022 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: Facility ID: 293294 Type: WELL API Number: 067-09419 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 07/21/2022 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Pass	Ditches	Pass			
Ditches	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Containers within containment.
Compaction	Pass	Gravel	Pass			
Gravel	Pass					

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403519639	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6240946
712700591	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6240927