

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/11/2023

Submitted Date:

09/12/2023

Document Number:

712700640

FIELD INSPECTION FORMLoc ID 333564 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

20 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215235	WELL	PR	05/01/2020	CBM	067-06840	ZELLITTI 1 A	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location				
Lease Road:				
Type	Access			
comment:	Location gated, off of private road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	Labels and signs on tank and separators			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Metal sign posted at location entrance.			
Corrective Action:				Date:
Type	CONTAINERS			
Comment:	Labels on containers.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted on wellhead sign.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Observed impacted material around wellheads, and muffler outlets.			
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002..(2).D.			Date: 09/18/2023
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Metal mesh cage.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Cattle panel enclosure around wellhead, pumpjack, telemetry, and prime mover.			
Corrective Action:				Date:
Type	LOCATION			
Comment:	T-post and barbed wire.			
Corrective Action:				Date:

Type	SEPARATOR		
Comment:	Cattle panel enclosure around separators, meterhouse, tank, and telemetry.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 2		
Comment:	3" lines from separator to meterhouse. Calibration date 7/30/2023 & 7/31/2023.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 4		
Comment:	2-3" lines from wellhead to separator. 2-1" lines from separator to prime mover.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	PVC access		
Corrective Action:		Date:	
Type: Gathering Line	# 1		
Comment:	Buired valve can, above ground valves.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Natural gas motor		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

PRODUCED WATER	1	<100 BBLs	PBV STEEL		37.149430,-107.809220	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Wells Served By Facilities Above						
API Number		API Number		AirsID		
067-09384						
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	215235	Type:	WELL	API Number:	067-06840	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	07/21/2022	Annual Brhd Completed?	No						
Last Brhd Test Results	Initial Surf Csg Pressure:	3	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel				
Compaction	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Containers within containment.
Gravel	Pass	Ditches	Pass			

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700644	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6247985