

# Inspection Photos

API: 011-06099

Operator: PONCHO PRODUCTION COMPANY

Inspection Date: 9/6/2023



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southwest along the former access road. The road has not been reclaimed and consists of undesirable weed such as Kochia and Russian thistle.



## Inspection Photos



**Photo 2.** Facing south toward the location which has not been reclaimed. There are undesirable weeds throughout the location and areas bare vegetation. There is equipment that remains at the south side of the location shown at red arrow.



## Inspection Photos



**Photo 3.** Facing northeast. This area appears to be the former tank battery site. There are likely soil issues preventing vegetation growth within this area.



## Inspection Photos



**Photo 4.** Facing southeast at the south side of the location. There is an abandoned pipe riser that has not been removed. The area around the riser is mostly bare of vegetation and has not been reclaimed. Previous corrective action was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API: 011-06099 | Date: 9/6/2023

## Inspection Photos



**Photo 5.** Facing south at the surrounding undisturbed reference area which shows a uniform vegetation cover consisting of Blue grama, Sand dropseed, Prairie threeawn among other species.

