

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/12/2023

Submitted Date:

09/12/2023

Document Number:

712700647

**FIELD INSPECTION FORM**Loc ID 334338 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

21 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276393	WELL	PR	03/04/2005	CBM	067-09021	KNIGHT E 2	PR
300108	WELL	PR	09/17/2013	CBM	067-09654	KNIGHT E 3	PR

**General Comment:**

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Locked gate, 2C40 key.		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Metal sign posted at location entrance. Missing a wellhead identification sign for the #3 well. See Photo #5.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	11/13/2023
Type	TANK LABELS/PLACARDS		
Comment:	Contents and volume labels, NFPA placards on produced water tanks.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Warning signs on pumpjacks, NFPA placards on separators.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Posted on wellhead sign.

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Cattle panel enclosure around separator, telemetry, produced water tank, and telemetry.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	T-post and barbed wire.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panel enclosure around wellhead, pumpjack, and electrical service box.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal mesh cage.		
Corrective Action:		Date:	
Type	OTHER		

Comment:	Cattle panel enclosure around electrical transformer, and cathodic protection.			Date:	
Corrective Action:				Date:	
<b>Equipment:</b>				corrective date	
Type: Gas Meter Run	# 2				
Comment:	3" line from separator to meterhouse. Calibration date 7/10/2023.			Date:	
Corrective Action:				Date:	
Type: Pump Jack	# 2				
Comment:				Date:	
Corrective Action:				Date:	
Type: Ancillary equipment	# 2				
Comment:	Wellhead			Date:	
Corrective Action:				Date:	
Type: Prime Mover	# 2				
Comment:	Electrical motor			Date:	
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 2				
Comment:				Date:	
Corrective Action:				Date:	
Type: Bird Protectors	# 2				
Comment:	On separator vent stack.			Date:	
Corrective Action:				Date:	
Type: Gathering Line	# 2				
Comment:	Buried valve can.			Date:	
Corrective Action:				Date:	
Type: Flow Line	# 2				
Comment:	3" line from wellhead to separator.			Date:	
Corrective Action:				Date:	
Type: Bradenhead	# 2				
Comment:	PVC access			Date:	
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.201450,-107.610070
Comment:					
Corrective Action:					
Date:					

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type) _____					
<b><u>Berms</u></b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date: _____
<b><u>Wells Served By Facilities Above</u></b>					
API Number		<b><u>AirsID</u></b>			
067-09654		API Number	AirsID		
<b><u>Venting:</u></b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date: _____
<b><u>Flaring:</u></b>					
Type					
Comment:					
Corrective Action:					Date: _____

**Inspected Facilities**Facility ID: 276393 Type: WELL API Number: 067-09021 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 04/27/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 22 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: Facility ID: 300108 Type: WELL API Number: 067-09654 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 05/04/2023 Annual Brhd Completed? Last Brhd Test Results Initial Surf Csg Pressure: 132 Fluid Type: End Surf Csg Pressure: --Comment: Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass			
Rip Rap	Pass	Ditches	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Wellheads #1 & #3 production equipment is grouped together. Wellhead #2 production equipment is separate.	pattillc	09/12/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700651	Well Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6248988">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6248988</a>