

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/12/2023

Submitted Date:

09/12/2023

Document Number:

713300086

FIELD INSPECTION FORMLoc ID 317969 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All inspections
Silver, Randy		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240273	WELL	PR	04/01/2023	OW	123-08061	ROCKY MOUNTAIN FUEL CO C 6	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	disassembled pumping unit on site		
Corrective Action:	Comply with Rule 606	Date:	10/12/2023
Type	WEEDS		
Comment:	overgrown vegetation around location and equipment		
Corrective Action:	Comply with Rule 606	Date:	10/12/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 1		
Comment:	line heater		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	disassemble on site with out prime mover		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected FacilitiesFacility ID: 240273 Type: WELL API Number: 123-08061 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: at time of inspection well appeared to be shut inCorrective Action: Date: **BradenHead**Date of Last Brhd Test: 01/27/2023Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Tuesday 9-12-2023 at approximately 10:00, I, Inspector Michael Kester, conducted an on-site inspection.</p> <p>Location: Rocky Mountain Fuel CO C 6</p> <p>Operator: KPK</p> <p>API#: 123-08061</p> <p>County: Weld</p> <p>While there, I observed well that appeared to be shut in.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds, Rule 606, corrective action date, 10-12-2023</p> <p>Unused equipment, Rule 606, corrective action date, 10-12-2023</p> <p>See attached photo # 1, 2, 3, & 4</p> <p>Weather conditions: dry and sunny</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the COGCC</p>	kesterm	09/12/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300087	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6249795